

## WBGT値と気温・相対湿度の関係

		相対湿度(%)																
		20	25	30	35	40	45	50	55	60	65	70	75	80	85	90	95	100
気温(°C)(乾球温度)	40	29	30	31	32	33	34	35	35	36	37	38	39	40	41	42	43	44
	39	28	29	30	31	32	33	34	35	35	36	37	38	39	40	41	43	43
	38	28	28	29	30	31	32	33	34	35	35	36	37	38	39	40	42	42
	37	27	28	29	29	30	31	32	33	34	35	35	36	37	38	39	41	41
	36	26	27	28	29	29	30	31	32	33	34	34	35	36	37	38	39	39
	35	25	26	27	28	29	29	30	31	32	33	33	34	35	36	37	38	38
	34	25	25	26	27	28	29	29	30	31	32	33	33	34	35	36	37	37
	33	24	25	25	26	27	28	28	29	30	31	32	32	33	34	35	35	36
	32	23	24	25	25	26	27	28	28	29	30	31	31	32	33	34	34	35
	31	22	23	24	24	25	26	27	27	28	29	30	30	31	32	33	33	34
	30	21	22	23	24	24	25	26	27	27	28	29	29	30	31	32	32	33
	29	21	21	22	23	24	24	25	26	26	27	28	29	29	30	31	31	32
	28	20	21	21	22	23	23	24	25	25	26	27	28	28	29	30	30	31
	27	19	20	21	21	22	23	23	24	25	25	26	27	27	28	29	29	30
	26	18	19	20	20	21	22	22	23	24	24	25	26	26	27	28	28	29
	25	18	18	19	20	20	21	22	22	23	23	24	25	25	26	27	27	28
	24	17	18	18	19	19	20	21	21	22	22	23	24	24	25	26	26	27
	23	16	17	17	18	19	19	20	20	21	22	22	23	23	24	25	25	26
22	15	16	17	17	18	18	19	19	20	21	21	22	22	23	24	24	25	
21	15	15	16	16	17	17	18	19	19	20	20	21	21	22	23	23	24	

WBGT値	注 意 25°C未満	警 戒 25°C~28°C	嚴重警戒 28°C~31°C	危 険 31°C以上
-------	---------------	------------------	-------------------	---------------

(ここで、28°C~31°Cは、28°C以上31°C未満の意味)

(日本生気象学会『日常生活における熱中症予防指針』Ver. 1 2008. 4から)

※ 危険・嚴重警戒などの分類は、日常生活上での基準であって、労働の場における熱中症予防の基準にはあてはまらないことに注意が必要です、